PATENT

Docket No.: APPL-P3208

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

RECEIVED

Group Art Unit: 2836

Examiner: Leja, Ronald W.

CENTRAL FAX CENTER

Serial No. 10/749,809

Filed: December 31, 2003

FEB 2 7 2006

In re Application of: Teener et al.

For:

POWER ON SEQUENCE AND GROUND FAULT INTERRUPTER FOR

HOT PLUG DEVICE

Certificate of Facsimile Transmission

I hereby certify that this of pespyndence is being transmitted via Facsimile to (571) 273-8300, on

Signed Stephanie Davis

TRANSMITTAL LETTER

Mail Stop Issue Fee Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

Dear Sir.

Enclosed please find an Amendment After Allowance in connection with the above-identified application.

In the event the Patent Office charges a fee for filing the above-noted documents, including any fees required under 37 CFR 1.136 for any necessary Extension of Time to make the filing of the attached documents timely, the Assistant Commissioner is hereby authorized to charge or credit the difference to our Deposit Account No. 50-0612. An additional copy of this page is enclosed.

Respectfully submitted,

SIERRA PATENT GROUP, LTD.

Dated: February 27, 2006

John W. Crosby Reg. No. 49,058

Sierra Patent Group, Ltd. 1657 Hwy 395, Suite 202 Minden, NV 89423

(775) 586-9500

PATENT

Docket No.: APPL-P3208

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE CENTRAL FAX CENTER

Group Art Unit: 2836

Examiner: Leja, Ronald W.

FEB 2 7 2006

Serial No. 10/749,809

Filed: December 31, 2003

In re Application of: Teener et al.

POWER ON SEQUENCE AND GROUND FAULT INTERRUPTER FOR

HOT PLUG DEVICE

Certificate of Facsimile Transmission hereby certify that this correspondence is being transmitted via Facsimile to (571) 273-8300, on

AMENDMENT AFTER ALLOWANCE PURSUANT TO 37 CFR 1.312

Mail Stop Issue Fees Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

Dear Sir:

Applicants hereby amend the application to correct a typographical and/or grammatical error as follows:

Docket No.: APPL-P3208

In the Title

Kindly amend the title as follows:

POWER ON SEQUENCE AND GROUND FAULT INTERRUPTOR INTERRUPTER
FOR HOT PLUG DEVICE